

# Annual Rust Protection Inspection

RustFax Certified Inspection Report — Form RI-2025-A

✓ **PASS**

Report #INS-2025-04172

## Vehicle Information

VIN1FMSK8DH9LGA12345

YEAR / MAKE / MODEL 2020 Ford Explorer XLT

BODY STYLE SUV

COLOR White

ODOMETER 62,418 miles

INSPECTION DATE April 17, 2025

INSPECTOR Brian Kowalski

NEXT DUE April 2026

## Applicator Information

BUSINESS Cascade Undercoating Co.

LOCATION Seattle, WA

PHONE (206) 555-0147

CERTIFICATION #CUC-2019-0042

## Undercarriage Inspection

AREA	CONDITION	COATING COVERAGE	CORROSION	NOTES
Frame Rails (Left)	PASS	95%	None detected	Coating intact, no wear
Frame Rails (Right)	PASS	95%	None detected	Coating intact, no wear
Cross Members	PASS	90%	None detected	Minor road debris impact, recoated
Wheel Wells (Front)	PASS	85%	None detected	High-wear area, thinning near edges
Wheel Wells (Rear)	PASS	85%	None detected	Normal wear pattern
Rocker Panels	PASS	90%	None detected	Good condition
Fuel Tank Straps	PASS	80%	None detected	Recoated during inspection
Brake Lines	PASS	90%	None detected	No flaking or rust
Exhaust Hangers	PASS	75%	Surface only	Heat-affected zone, expected
Suspension Components	PASS	80%	None detected	Coil springs and control arms coated

# Annual Rust Protection Inspection

## Body Panel Inspection

AREA	CONDITION	CORROSION	NOTES
Door Bottoms (All)	PASS	None detected	Drain holes clear, inner cavities treated
Hood Inner	PASS	None detected	Factory treatment supplemented
Tailgate / Liftgate	PASS	None detected	Inner seams treated
Fender Liners	PASS	None detected	Liners intact, underside coated
Quarter Panels	PASS	None detected	Inner cavities treated, no bubbling

## Overall Assessment

**Result:** **PASS** — Comprehensive 4-year inspection  
**Coating Coverage:** 80% on high-wear areas, 95% on protected areas  
**Corrosion Found:** Zero corrosion on any inspected surface  
**Structural Condition:** Vehicle in excellent structural condition  
**Recommendation:** Next full re-application recommended by March 2027. Annual inspection due April 2026.

## Work Performed During Inspection

SERVICE	DETAIL
Touch-up coating	Cross members, fuel tank straps, exhaust hanger area
Drain hole clearance	All door bottoms, rocker panel weep holes checked and cleared
Cavity wax	Refreshed inner door cavities and quarter panel seams

## Inspection History

DATE	ODOMETER	RESULT	APPLICATOR
April 2025	62,418 mi	PASS	Cascade Undercoating Co., Seattle, WA
March 2024	49,210 mi	PASS	Cascade Undercoating Co., Seattle, WA
February 2023	35,880 mi	PASS	Pacific NW Rust Shield, Portland, OR
January 2022	22,150 mi	PASS	Pacific NW Rust Shield, Portland, OR

Inspector Signature

Vehicle Owner / Representative